

# Crookwell 3 Wind Farm Site Analysis




Figure 1: Site Analysis

## Site Photos Crookwell 3 South



1. View east to Pejar Dam from landowners dwelling



2. Typical landscape of Crookwell 3 South



3. Drainage line



4. Planted wind break



5. Rocky hilltop



6. Transmission line from highest point



7. Looking north from centre of Crookwell 3 South



8. Wind mill and shed



9. Yellow Box (remnant vegetation)

## Site Photos Crookwell 3 East



1. View to Dam from Boltons Road



2. Leeston Homestead



3. Typical landscape from hilltop



4. Pigman's Hill from hilltop



5. View east with Dam in foreground



6. Intersection of Bolton's Road and property boundary



7. View south along drainage line to Dam



8. Hillview Homestead



9. Site from western access point



10. Fenced reserve



11. View south from northern boundary



12. Dam with Willowvale Hill in background



13. View to non-participating dwellings from northern boundary



14. Potential access road at eastern boundary



15. View west from central southern portion of site